

CERTIFICATE OF COMPLIANCE

Certificate Number E184471
Report Reference E184471-20061011
Issue Date 2020-MARCH-12

Issued to: Solutions Industry & Building
25 Rue Theophile Somborn
57220 Boulay FRANCE

**This certificate confirms that
representative samples of**

OUTLET BUSHINGS AND FITTINGS
See Addendum Page


Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 514B - Conduit, Tubing and Cable Fittings.
Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information.

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E184471
Report Reference E184471-20061011
Issue Date 2020-MARCH-12

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Cord Connectors, Cat. Nos.

Metric Hub Long Threads, F 7031 600, F 7031 609, F 7031 650, F 7031 659, F 7032 000, F 7032 009, F 7032 050, F 7032 059, F 7032 500, F 7032 509, F 7032 550, F 7032 559, F 7033 200, F 7033 209, F 7034 000, F 7034 009, F 7035 000, F 7035 009, F 7036 309, F 7036 300, F7431200E, F7431650E, F7431600E, F7432050E, F7432000E, F7432550E, F7432500E, F7433200E, F 7434 000E, F 7435 000E, F 7436 300E, F8031200E, F 8031 600, F8031600E, F 8031 650, F8031650E, F 8032 000, F8032000E, F 8032 050, F8032050E, F 8032 500, F8032500E, F 8032 550, F8032550E, F 8033 200, F8033200E, F 8034 000, F 8034 000E, F 8035 000, F 8035 000E, F 8036 300, F 8036 300E.

Metric Hub Long Threads, F 7031 640, F 7031 660, F 7031 649, F 7031 669, F 7032 040, F 7032 049, F 7032 060, F 7032 069, F 7032 540, F 7032 549, F 7032 560, F 7032 569, F 7033 240, F 7033 249, F 7034 040, F 7434 040E, F 7034 049, F 7035 040, F 7435 040E, F 7035 049, F 7036 340, F 7036 349, F7431240E, F7431660E, F7432060E, F7432040E, F7432560E, F7432540E, F7433240E, F 7436 340E, F8031240E, F 8031 640, F 8031 660, F8031660E, F 8032 040, F8032040E, F 8032 060, F8032060E, F 8032 540, F8032540E, F 8032 560, F8032560E, F 8033 240, F8033240E, F 8034 040, F 8034 040E, F 8035 040, F 8035 040E, F 8036 340, F 8036 340E.

PG Hub Standard Threads, F 7000 900, F 7000 909, F 7001 100, F 7001 109, F 7001 300, F 7001 309, F 7001 600, F 7001 609, F 7002 100, F 7002 109, F 7002 900, F 7002 909, F 7003 600, F 7003 609, F 7004 200, F 7004 209, F 7004 900, F 7004 909, F7400700E, F7400900E, F7401100E, F7401300E, F7401600E, F7402100E, F7402900E, F 7403 600E, F 7404 200E, F 7404 900E, F8000700E, F 8000 900, F8000900E, F 8001 100, F8001100E, F 8001 300, F8001300E, F 8001 600, F8001600E, F 8002 100, F8002100E, F 8002 900, F8002900E, F 8003 600, F 8003 600E, F 8004 200, F 8004 200E, F 8004 900, F 8004 900E.

PG Hub Standard Threads, F 7000 940, F 7000 949, F 7001 140, F 7001 149, F 7001 340, F 7001 349, F 7001 640, F 7001 649, F 7002 140, F 7002 149, F 7002 940, F 7002 949, F 7003 640, F 7003 649, F 7004 240, F 7004 249, F 7004 940, F 7004 949, F7400740E, F7400940E, F7401340E, F7401640E, F7402140E, F7402940E, F 7403 640E, F 7404 240E, F 7404 940E, F8000740E, F 8000 940, F8000940E, F 8001 140, F 8001 340, F8001340E, F 8001 640, F8001640E, F 8002 140, F8002140E, F 8002 940, F8002940E, F 8003 640, F 8003 640E, F 8004 240, F 8004 240E, F 8004 940, F 8004 940E.

Metric Hub Std Threads, F 7021 650, F 7021 659, F 7021 600, F 7021 609, F 7022 000, F 7022 009, F 7022 050, F 7022 059, F 7022 500, F 7022 509, F 7022 550, F 7022 559, F 7023 200, F 7023 209, F 7024 000, F 7024 009, F 7025 000, F 7025 009, F 7026 300, F 7026 309, F7421200E, F7421650E, F7421600E, F7422050E, F7422000E, F7422550E, F7422500E, F7423200E, F 7424 000E, F 7425 000E, F 7426 300E, F8021200E, F 8021 600, F8021600E, F 8021 650, F8021650E, F 8022 000, F8022000E, F 8022 050, F8022050E, F 8022 500, F8022500E, F 8022 550, F8022550E,



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E184471
Report Reference E184471-20061011
Issue Date 2020-MARCH-12

F 8023 200, F8023200E, F 8024 000, F 8024 000E, F 8025 000, F 8025 000E, F 8026 300, F 8026 300E.

Metric Hub Std Threads, F 7021 660, F 7021 669, F 7021 640, F 7021 649, F 7022 060, F 7022 069, F 7022 040, F 7022 049, F 7022 540, F 7022 549, F 7022 560, F 7022 569, F 7023 240, F 7023 249, F 7024 040, F 7024 049, F 7025 040, F 7025 049, F 7026 340, F 7026 349, F7421240E, F7421660E, F7422060E, F7422040E, F7422560E, F7422540E, F7423240E, F 7424 040E, F 7425 040E, F 7426 340E, F8021240E, F 8021 640, F 8021 660, F8021660E, F 8022 040, F8022040E, F 8022 060, F8022060E, F 8022 540, F8022540E, F 8022 560, F8022560E, F 8023 240, F8023240E, F 8024 040, F 8024 040E, F 8025 040, F 8025 040E, F 8026 340, F 8026 340E.

NPT Hub Threads, F 7040 800, F 7040 809, F 7041 200, F 7041 209, F 7042 000, F 7042 009, F 7042 800, F 7042 809, F7440800E, F7441200E, F7442000E, F7442800E, F 8040 800, F8040800E, F 8041 200, F8041200E, F 8042 000, F8042000E, F 8042 800 F8042800E.

NPT Hub Threads, F 7040 840, F 7040 849, F 7041 240, F 7041 249, F 7042 040, F 7042 049, F 7042 840, F 7042 849, F7440840E, F7441240E, F442040E, F 8040 840, F8040840E, F 8041 240, F8041240E, F 8042 040, F8042040E, F 8042 840.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

